

EXCEEDENCE TRACKING
May 6 – May 19, 2003

According to the Washington Department of Ecology TDG variance for 2003 spill season, the Corps is required to provided the following information on exceedences of the 120% TDG in tailwater and 115% TDG in forebay water quality standards:

1. Date and times of exceedence
2. Amount of exceedence in percent saturation
3. Explain reason for exceedence
4. Discuss steps taken to fix the problem.

In order to provide the above information, the Corps has developed the following draft list of reasons that exceedences occur.

TDG EXCEEDENCE TRACKING
Types of Exceedences:
1. Exceedence due to high runoff flows and flood control efforts
2. Exceedence due to Intertie line outages
3. Exceedence due to unit outages during repair or maintance
4. Exceedence due to BPA is unable to handle load so they had to spill
5. Exceedence due to a break down in communication. Teletype went out but no change occurred.
6. Exceedence due to uncertainties when using best professional judgement to apply the spill guidance criteria (travel time; degassing; water temperature effects; spill patterns)
7. Exceedence due to high TDG levels coming from the Mid Columbia (see Pasco FMS readings).
8. Exceedence due to a load rejection, the powerhouse was not working and the river was spilled.
9. Exceedence due to lack of information: the FMS gage was not working and we had no information

Exceedences are being tracked and the following table shows the results for May 6 – 19, 2003.

