The Dalles Dam

TDA Wire Rope Replacement – severed strands



New Jacking assembly

Pendant frames used in 2005

Pendants

Spillgate (typ.)



Stoplogs Not Shown

Pendants – Jacking frame layout to raise gates to dewater bay