Table TDA 6. 2010 Spill Pattern. 8/9 Spill Patterns (Revised April 20, 2010).
The highlighted spillbays are redtagged and unavailable for normal use.

Spill patterns have been refined (0.2 and 0.7 foot increments) based on the gate counter, which is used to set gate openings in the control rool. Refinement was stopped once spill was plus or minus 1% of the required 40%.

The Dalles

Discharge Distribution Patterns

| Spillway Bay Number | | |