

FPP Change Form

Change Request Number: 10LGS004

Date: Jan 11, 2010

Proposed by: CENWW-OD-T

Proposed Change:

Section 2.1.2.

Involuntary spill at Little Goose is the result of river flow exceeding powerhouse capacity, insufficient generation loads to pass the river flow, turbine unit outages (forced or scheduled), or the failure of a key component of the juvenile fish passage facility which forces the project to spill to provide juvenile fish passage. Spill at Little Goose shall be distributed in accordance with the spill patterns included at the end of this section, Table LGS-10, 11, and 12. Special spills for juvenile fish passage will be provided as detailed in **Appendices A and E.**

Deleted: 9

Deleted: , pending development of a "high gate" spill pattern.

Reason for Change:

Updating the section.

Comments from others:

(Space for comments by others)

Record of Final Action:

(What action was finally decided upon?)

FPOM approved 1/13/10