

**FPP Change Request Form**

**Change Form # & Title:** 15IHR007 – Spill Pattern Correction  
**Date Submitted:** April 22, 2015  
**Project:** IHR  
**Requester Name, Agency:** Lisa Wright, COE RCC  
**Final Action:** APPROVED – [May 14, 2015](#)

**FPP Section:** IHR Table IHR-9\*. Spill Patterns with RSW for 30% Spill.

\*[Note that this table will change to IHR-10, due to change form 15IHR006 that adds a new table for Unit 3 fixed blade operating range.]

**Justification for Change:** During a comparison of spill pattern tables in the FPP versus the patterns programmed into GDACS, an error was noted in Table IHR-9\* for 30% spill w/ RSW. The pattern with 51 total gate stops should have Bay 3 open 7 stops (not 8). This was a copy/paste error that occurred when the table was reformatted in 2012. However, the correct pattern is programmed into GDACS so this error has not had an impact on project operations.

**Proposed Changes:**

**Table IHR-109. Ice Harbor Dam Spill Patterns with RSW for 30% Spill.**

Total Outflow (kcfs)	Total Spill		IHR Spill Patterns – 30% Spill (# Gate Stops/Spillbay)										Total Stops (#)
	(kcfs)	(%)	1	2 RSW	3	4	5	6	7	8	9	10	
178.2	95.1	53.4%		RSW	87	7	7	7	7	7	7	2	51

**Comments from others:**

**Record of Final Action:**

APPROVED at FPOM meeting May 14, 2015