

John Day Dam Unit Operating Priority 2008

Existing 2007 Priority: 5, 1, 2, 3, 4, then 6-16 in any order.

Recommended 2008 Priority: 5, 1, 3, 16, 14, 12, 10, 8, 15, 2, 11, 7, 4, 13, 9, 6.

Reason for Change: The recommended change will improve forebay attraction flow for the TSWs while maintaining adequate water velocity at the juvenile bypass outfall.